SUIF

P 152052Z AUG 68
FM NPIC WASHDC
TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCLFGA/100TH SRW OL 19 MCCOY AFB FLA
RUWJDBA/100TH SRW DAVIS MONTHAN AFB ARIZ
RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD
RUEAIIA/CIA WASH DC
RUEOJFA/DIA ATTN: DIAXX-2
RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF
RUEFHQA/HQS USAF
BT

115 Aug 68 21 027

OUT 65722

SECRET CITE NPIC 4370.

SAC FOR DIR, DOSR, DISD; 15TH AF FOR DI. DO; 100TH SRW FOR CO, DCOI; HQ USAF FOR AFRDR

25X1

FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

SUBJECT: EVALUATION OF GLASS LAMP MISSION G-037, 13 AUGUST 1968.

1. QUALITY SUMMARY: THIS MISSION PROVIDES IMAGERY OF BETTER QUALITY THAN RECENT MISSIONS UTILIZING UNIT B-18. EVEN THOUGH THE IMAGERY THROUGHOUT THE MISSION APPEARS SLIGHTLY SOFT, POSSIBLY VIBRATION INDUCED, THE GROUND RESOLUTION AND INTERPRETATION SUITA-

PAGE 2 RUEADJU 50 S E C R E T BILITY ARE CONSIDERED GOOD. CLOUD COVER AND HAZE OBSCURE 10 PERCENT OF THE ENTIRE MISSION.

2. MISSION DATA:
A. STANDARD "B" CAMERA, NUMBER B-18 WAS EMPLOYED. THIS WAS AN OPERATIONAL MISSION USING A U-2 AIRCRAFT. MODE V WAS USED THROUGHOUT.

B. FILM TYPE 3400 WAS EMPLOYED. PROCESSING WAS ACCOMPLIS BY NAV RECON TECH SUPPCEN. ALL MATERIAL WAS PROCESSED TO A Ø. GAMMA SPEED OF BAR 2.32 (LOG E).

3. ORIGINAL NEGATIVE:

A. EXPOSURE APPEARS ADEQUATE.

B. DENSITY AND CONTRAST ARE MEDIUM.

. IMAGED DEGRADATIONS:

(1) 9R SIDE: INBOARD AND OUTBOARD ROLLER CHATTER ARE PRESENT INTERMITTENTLY THROUGHOUT. A NARROW PLUS DENSITY STREAK LOCATED 4.1 INCHES FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT FROM FRAME 1795 TO THE END OF THE MISSION.

(2) 9L SIDE: A FOUR INCH LONG WEDGE-SHAPED FOG PATTERN ENTERS THE ACTIVE FORMAT FROM THE TITLED EDGE, FOUR INCHES FROM THE LEFT FORMAT EDGE ON FRAME Ø244. THOSE FRAMES THAT

PAGE 3 RUEADJU 50 S E C R E T CONTAIN UNIFORM DENSITY AREAS EXHIBIT SUBTLE FOG PATTERNS. THE FIRST IS LOCATED ONE INCH FROM THE DATA BLOCK EDGE, THE SECOND, THREE INCHES FROM THE RIGHT FORMAT EDGE AND ONE INCH FROM THE TITLED EDGE.

(3) BOTH SIDES: MINOR FOG, LOCATED IN THE VICINITY OF THE VERTICAL INDICATOR DOT IS PRESENT ON ALL FRAMES.

D. PHYSICAL DEGRADATIONS:

(1) 9R SIDE: A HEAT SPLICE IS LOCATED IN FRAME 919 AND A MANUFACTURER'S SPLICE IN 1093.

CX	OFFICE	
7	FILE	
IED.	CABLE SEC.	2
S	PP&B/RD	
	SECUR.	
34	TSSG / TAP	4
1		
	PSG/OC	
	RRD	
	REPRO	
	AID	
	IEG	
	PROD	
	SCIEN	
	WEST	
	EAST	
	M&S	
	PGM	
	IAS	
	DIA-XX4	
	SPAD	
	DIA-AP	
	25)	< 1
	CMX	

DISTRIBUTION

ADVARGE CY CARACTER TARE STEE

8

(2) 9L SIDE: A HEAT SPLICE IS LOCATED IN FRAME 911. E. AUXILIARY DATA:

(1) 9R SIDE: ALL IR POSITION INDICATORS ARE FAINTLY IMAGED.
(2) 9L SIDE: THE IR POSITION INDICATOR VARIES FROM FAINT
TO PROPERLY EXPOSED. IT IS NOT IMAGED ON FRAME 1314.

(3) BOTH SIDES: ALL OTHER AUXILIARY DATA FUNCTIONED

PROPERLY.

F. OTHER DATA: LAST TITLED FRAME ON BOTH SIDES IS 2056.
4. POSITIVES: PRINTING AND PROCESSING ARE GOOD.

GP-1

SECRET

END OF MESSAGE